



PEUGEOT Boxer fg tôlé Asphalt 333 L1H1: FL-465-GB

Vinnumber:	VF3YBBNFA12M50099	Versionname:	
First Registrationdate:	30/10/2019	Fiscalpower:	
Expertise Mileage:	142896	Power Kw:	
Bodytype:	Transporter	Body colour:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Steel
Maintenance:	OK	Dashboard color:	Black
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total:	2	Tow bar	
Number keys remote:	1	Radio	
Windows electric F:		Central consol F:	
Cruise Control:		Rear parking sensors:	
Steering wheel multifunctional:		Sliding door right-side:	
Couleur correcte ?		Rear view camera:	
Couleur correcte ?	bleu	Seat cover lining:	Lining Other
Type of climate control:	Manual climate control		

Degree of wear

215/70/15/109 S				
Summer tyres:	Fr.L.	Other: 8 mm	Fr.R.	Other: 8,5 mm
	Re.L.	Other: 5,2 mm	Re.R.	Other: 6 mm
Tyre profile depth FL				8.0
Tyre profile depth FR				8.5
Tyre profile depth RL				5.2
Tyre profile depth RR				6.0
Tyre size FL				215/70 R 15 109 S
Tyre size FR				215/70 R 15 109 S
Tyre size RL				215/70 R 15 109 S
Tyre size RR				215/70 R 15 109 S
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				263
Tyre make FR				263
Tyre make RL				263
Tyre make RR				263

Assistance equipment

Spare wheel	Yes	Jack	Yes
GPS disc, Not functioning (well), Check			



Seat cover FL, Not original part, Acceptable



Side panel L, Dent(s), Acceptable



Car body corner RL, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Outside rear-view mirror housing R, Scratch(es), Repair/replace (lump sum)



Sliding door R, Dent(s), Repair and paint (complete)



Wing FR, Scratch(es), Paint



Bumper corner RL, Scratch(es), Acceptable



Boot door panel RL, Scratch(es), Paint



Boot door panel RR, Scratch(es), Acceptable



Fuel cap cover, Scratch(es), Paint



Bodywork, Not original part, Remove lettering

